


MRMA4301 Cable Saddle with Velcro Straps

DO NOT OVER TIGHTEN BOLT
ASSEMBLY NEEDS TO SWIVEL



HOSE
TROLLEY

TR2000
RAIL

